

WS-1

CRUTCH

WM-4

B

1/8" PLY BOTTOM

HINGE

F-6B

ORBIT LOCATION →

F-6

PUSH ROD TO
DUMPER

