



L STRUTS
SHEET SPRUCE



ALL RIGGING & CONTROL
HEAVY WEIGHT "LAYSTR"



RIGGING WIRES SINGLE, F
DOUBLE. ALL RIGGING-W
CROSS SHOULD BE SOFT
THAT POINT TO AVOID R

SCHEMATIC DIAGRAM
TYPE B POSITION
RIGGING WIRE ATTA